

## **VEGAMET 391**

Version, available since	Description
1.60.0, 02/2016	New functions:
02/2016	- Input:
	<ul> <li>For VEGA HART sensors, selection of the HART variables as sensor value possible</li> </ul>
	- Relay outputs:
	<ul> <li>Default settings of relays modified: Rel. 1 is assigned with mode overfill protection, Rel. 25 are deactivated, Rel. 6 is activated as fail safe relay</li> <li>Relay can be activated/deactivated via menu</li> <li>Pump control with new options:</li> <li>Sequenced/Alternating pump operation</li> <li>Dry weather pump</li> <li>Bandwidth for switching points</li> <li>Counter for switch-on processes of the relays</li> </ul>
	<ul><li>Signal conditioning:</li></ul>
	<ul> <li>Display unit m(d) replaced by m</li> <li>2. Totalizer can be activated for flow volume measurement</li> </ul>
	- VEGA Inventory System:
	<ul> <li>Presentation of the SIM-ID / Location data on HTML page (only valid in conjunction with LUCOM-Router)</li> <li>Transmission of the SIM-ID / Location data (only valid in conjunction with LUCOM-Router)</li> <li>Order list VIS: Transmitting interval can be changed via VIS surface</li> <li>Encrypted data transmission by means of TLS/PSK procedure to VEGA Inventory System</li> <li>Snapshot memory (measured values given later to the VEGA Inventory System) can be deleted via the website index1.htm</li> </ul>
	- Ethernet interface:
	<ul> <li>Encrypted data transmission via Ethernet interface by means of TLS/PSK procedure to DTM</li> <li>Websites revised (Log files can be opened via index.htm, adjustment blocked via index1.htm page)</li> <li>Telnet access blocked by default</li> <li>Telnet, VEGA-ASCII and Modbus TCP can be blocked or released via website index1.htm</li> <li>Safety update SSL / TLS-Stack</li> </ul>
	Error corrections:
	<ul> <li>Serial number &gt;16777215 of VEGA HART sensors correctly displayed</li> </ul>





Version, available since	Description
	Various translations corrected in the menu
	<ul> <li>Deactivation of the PIN removed after voltage loss (activated PIN was no longer effective after voltage loss)</li> </ul>
1.40.0, 07/2014	New functions:
	- E-Mail encryption: SSL/TLS 1.2
	<ul> <li>Port numbers for SMTP, HTTP and POP3 editable</li> </ul>
	Error corrections:
	<ul><li>VV-File: Unit "% sol Vol" replaced by "lin%"</li></ul>
	<ul> <li>- Zipping of measured value and status files only on request</li> </ul>
1.30.0, 02/2013	New functions:
02,2010	- Input:
	<ul> <li>PROTRAC SIL versions are displayed in the device search</li> <li>Interface measurement with VEGAFLEX 80 series</li> </ul>
	- Relay output:
	Pump control: Option Forced switchover added
	- WEB-VV:
	<ul> <li>WEB-VV data transmission: Submission of measured values after an inaccurate transmission</li> </ul>
	- Signal conditioning:
	<ul> <li>Units for "ct/s", "ct" and density units with adjustment units for HART-Generic sensors added</li> </ul>
	<ul> <li>Units for "mNN", "ct/s", "ct" added with scaling units</li> </ul>
	<ul> <li>Local adjustment:</li> </ul>
	<ul> <li>Acknowledgement of pump disturbances via the menu simplified</li> <li>New measured value picture with symbols for pump control</li> </ul>
	- Ethernet-Interface:
	Proxy function added
	Error corrections:
	<ul> <li>E-mail transmission: Problems with POP before SMTP removed</li> </ul>
	<ul> <li>Smaller errors in the menu removed</li> </ul>
	<ul> <li>When retrieving device trend files via http not all values were transmitted</li> </ul>
	<ul> <li>Calibration date and hardware version were not stored correctly in the EEPROM</li> </ul>
	<ul> <li>Error with http request via Excel 2010 removed</li> </ul>
	<ul> <li>Instrument can no longer be operated via the menu after a reset Switch-on time relay</li> </ul>
	- With HART-Generic sensors, the texts for the adjustment units "mBar" and "bar" are





Version, available since	Description
	interchanged
	After a restart, the measured value picture for totalizer was no longer displayed
1.20.0, 06/2011	New functions:  - Input:
	<ul> <li>HART mode also for instruments without optional interface if the respective hardware is mounted (digital print with index -04, instrument HW Rev. 1.0.7)</li> <li>HART: Secondary Master can be connected</li> </ul>
	- WEB-VV:
	Extension WEB VV data transmission by type measured value controlled/time-controlled  WEB VV Functions by triggered via DTM with a data.
	<ul> <li>WEB VV Event can be triggered via DTM with a delay</li> <li>Test event can be triggered via DTM with a delay</li> <li>Improved feedback with message transmission</li> </ul>
	- RS232 interface with Modem:
	<ul> <li>Additional possibility to send AT-Strings to the modem</li> <li>SMS and e-mail can now be transmitted at the same time (are executed one after the other)</li> <li>Additional LOG files for data transmission with modem or via LAN</li> </ul>
	<ul> <li>Local adjustment:</li> </ul>
	The on-time counter can now be reset via the menu
	Error corrections:
	Accuracy of the real time clock with operating in LAN improved
	- WEB VV data can be sent in minute cycle, previously caused a restart of the instrument
	- When setting up the pump control, a restart is no longer required for the correct function
	<ul> <li>Reset of the on-time counter of the relays is now stored in the EEPROM</li> </ul>
	- PPP: With Dial-In, the dial-in functioned only once
	<ul> <li>Relay status information was not transmitted correctly via Modbus TCP</li> </ul>
	Trend recordings are corrected with time changes
1.10.0,	New functions:
11/2009	<ul> <li>Software update function via DTM</li> </ul>
	<ul> <li>Relay mode pump control 3 and 4</li> </ul>
	<ul> <li>Relay, current output: Pulse length for flow pulses changed to 350 ms</li> </ul>
	- Local adjustment:
	<ul> <li>New menu image for switch on period Rel. 14</li> <li>New menu image for sensor status</li> <li>NE107 status messages</li> </ul>





Version, available since	Description
	Error corrections:  - Phoenix Contact modem together with RS232 interface  - Coded WEB-VV data transmission
1.03.0, 06/2009	New functions:  - Webserver:  • HTML pages in French  Error corrections:  - Instrument trend recordings
1.01.0, 06/2009	Error corrections:  - WEB-VV Event  - Instrument trend recordings after power fail  - Local adjustment
1.0.0, 05/2009	First version  - Software update only possible via USB-Update software not via DTM

## Legend:

Name	Description
Version	<ul> <li>xx.yy.zz</li> <li>xx: Compatibility version. Will be increased if there is no compatibility to the version before. Range of values 099.</li> <li>yy: Functions extension version. Will be increased if new functions or modifications where carried out. A function extension version can include error corrections. Range of values 099.</li> <li>zz: Error correction version. Will be increased if only error corrections where made. Range of values 099.</li> </ul>
Available since	Month/Year